



Note 1: These features to be removed from landfill area prior to completion of soil remedy.  
Site Plan created from Arcadis CAD drawings received December 2015.  
Aerial imagery accessed via ArcGIS Online and provided by the United States Department of Agriculture on 11 February 2021.  
Image is dated 31 July 2015.

**Legend**

Areas of Particular Concern  
(to be capped or excavated) (7)

Potential Source Area to be Removed (1)

Areas Determined to be Partially  
Non-Vegetated During Field  
Inspection

Edge of landfilled wastes (dashed where  
approximate)

Great Swamp National Wildlife Refuge  
property boundary

Areas where surface water flow does not  
exhibit typical bed and bank morphology

Waste and debris observed on ground  
surface but not observed or anticipated  
below ground surface

Open water

4002000400 Feet

Location of APCs and  
Partially Non-Vegetated Areas

ROLLING KNOLLS LANDFILL SUPERFUND SITE  
CHATHAM, NEW JERSEY

Geosyntec

consultants

Princeton, NJ

March 2021

Figure  
5-1